### Street lighting update. 16/11/2021

### Replacement lights for reconnection.

1. WSL 19.3 LP061 o/s 13 Leighton Road



 UKPN advise that the supply has been reinstated. CU Phosco have been requested to reconnect the lantern and to supply a test certificate.
 No date for this has been given to date.

2. WSL 20.1 LP 059 o/s 39 Leighton Road



See \* Below.

3. WSL 19.2 LP108 o/s 19/21 Moorhills Road



See \* Below.

4. WSL 19.4 LP08Moorhills/Moorlands/ Moorlands Road junction.



See \* Below

<sup>\*</sup>There has been no progress with these three outstanding light reconnections. At last meeting the Council resolved to prepare a formal complaint about the service received from UKPN. This decision has been notified to UKPN and the formal complaint is in course of preparation

5. o/s 44 Dormer Avenue. The ICP's approached for quotes to reconnect the above streetlights have been requested to provide quotes for the transfer of service. We continue to await quotations from the three accredited ICP's. This is being followed up.

### Faulty/ failed lights

1. WSF 20.1 outside 16 Wantage Close.



This lamp was initially reported under warranty for an intermittent fault in January 2020. There have been several repeat episodes reported during 2020 and 2021. We received a report on 28<sup>th</sup> October that the lamp was now flashing continuously. Although the warranty expired in CU Phosco, the warranty company, were requested to arrange an emergency disconnection followed by repair. They were unable to assist and indicated that they would not be able to attend for some time. The Council engaged the services of Sparkx to arrange emergency disconnection.

Sparkx attended immediately and disconnected a light but this was in the wrong location. They attended again as soon as the error was identified to them to disconnect the correct light. (See Fault 5, below) They confirmed that they could provide an emergency repair on a 24hour basis. CU Phosco were again approached inviting them to engage alternative contractors who were able to attend within 24 hours to attend to this ongoing failure. Cu Phosco arranged the immediate repair. They were thanked for their prompt attention to the matter.





This has been reported as now working.

# 3. WSF21.4 LP111 Moorhills Road (behind 1/3William Bandy Close)



This was attended by a contractor and found to have a faulty waterlogged photocell which has been replaced and it is back in light.

# 4. SF21.3 LP090 o/s 57 Moorlands Road.



This was attended by a contractor and found to have a dead supply and damaged door. The door has been fixed back and cable tied but the dead supply needs to be attended by UKPN. This is being reported to UKPN. The need for a more permanent repair to the door is being investigated.

### 5. WSF 21.5 LP125 o/s 15 Wantage Crescent.



This is believed to possibly have been disconnected in error by Sparkx who were requested to carry out an emergency disconnection of the flashing lamp outside **16 Wantage Close.** Sparkx have been requested to confirm that they have reconnected the light they disconnected in error. It has not been reported as a fault for repair at this stage.

### 6. Small roundabout coming into Wing, junction of Stewkley.



There has been a report that there are still 3 lamps not working at the small roundabout coming into Wing, junction of Stewkley Rd, and 2 more going down towards the village hall just off the roundabout.

These streetlights are owned and maintained by Buckinghamshire Council to whom the problem of multiple lights being out has been reported several times.

John Furniss

Deputy Clerk
Wing Parish Council

16<sup>th</sup> November 2021