

Street lighting update. 21/01/2022

Replacement lights for reconnection.

1. WSL 19.3 LP061 o/s 13 Leighton Road



UKPN confirmed on 3rd November that the supply had been installed.

CU Phosco were informed that the supply had been installed and requested to attend to complete the reconnection and testing of the lantern. Following an inspection, it was confirmed that the light was still out. Enquiries with CUPhosco determined that there was no supply to the column when they reconnected the lantern.

The absence of a supply was immediately reported to UKPN on 8th December 2021. There has been no response to date. A follow up on this situation has been issued to UKPN operatives including higher management to whom the complaint will be submitted, when prepared. (See below*)

2. WSL 20.1 LP 059 o/s 39 Leighton Road



See * Below.

3. WSL 19.2 LP108 o/s 19/21 Moorhills Road



See * Below.

4. WSL 19.4 LP085Moorhills/Moorlands/ Moorlands Road junction.



See * Below

*There has been no significant progress with these three outstanding light reconnections. A formal complaint about the service received from UKPN is in course of preparation. We are continuing to press UKPN for replies and particularly to reinstate the services to 2,3 and 4 above.

5. WSL 21.1 LP153 o/s 44 Dormer Avenue.



The alternative Independent Connection Providers (ICPs) approached for quotes to reconnect the above streetlights were requested to provide quotes for the transfer of service.

One quote has been received from an alternative ICP.

For the Council to engage the services of the alternative ICP to arrange the reconnections an Asset Owners Agreement needs to be in place with UKPN. This is in progress with a different department of UKPN. If such an agreement is confirmed the Council will be in a position to employ an alternative ICP for supply connections to the streetlights.

Faulty/ failed lights

1. SF21.3 LP090 o/s 57 Moorlands Road.



This was attended by a contractor and found to have a dead supply and damaged door. The door has been fixed back and cable tied but the dead supply needs to be attended by UKPN. This has been reported to UKPN. The need for a more permanent repair to the door is being investigated.


2. WSF 21.5 LP125 o/s 15 Wantage Crescent.




This is believed to possibly have been disconnected in error by Sparkx who were requested to carry out an emergency disconnection of the flashing lamp outside **16 Wantage Close**. Sparkx have been requested to confirm that they have reconnected the light they disconnected in error. It has not been reported as a fault for repair at this stage.

An inspection is being carried out to establish whether this has been completed.

3. Small roundabout coming into Wing, junction of Stewkley.



Latest report from Buckinghamshire Council 19/11/21



New updates on Street light not working report

Thank you for your report. We are currently building a package of works where your report will be addressed when we are next in the area.

Thank you for taking the time to bring this matter to our attention.


State changed to: Action scheduled

Buckinghamshire Council

State changed to: In progress

Buckinghamshire Council

[Unsubscribe from alerts about this report](#)



A418 Roundabout with Stewkley Road and Stewkley Road

We have received reports that the streetlights in this area are still inoperative despite several previous reports and assurances that they would be given urgent attention. Please attend and repair all the defective lights without further delay.

The report's reference number is **40178604**. Please quote this if you need to contact the council about this report.

This email was sent automatically, from an unmonitored email account. Please do not reply to it.

No further update has been received.

John Furniss

Deputy Clerk
Wing Parish Council

21st January 2022