

Street lighting update. 14/2/22

Replacement lights for reconnection.

A formal complaint has been submitted to UKPN.

1. WSL 19.3 LP061 o/s 13 Leighton Road



UKPN reconnections were advised in December of the absence of a supply at this column after their reconnection works in October. They have declined to investigate this and suggested that the Council reports it as a fault. This was done.

The absence of a supply has been confirmed by UKPN Faults team after investigations on 1st February. We are advised that the Faults team are arranging for temporary traffic lights before re-attending to attend to the missing supply.

2. WSL 20.1 LP 059 o/s 39 Leighton Road



We have received an updated quote from UKPN and are taking steps to arrange this reconnection.(see * under WSL 21.1 LP153 o/s 44 Dormer Avenue below)

3. WSL 19.2 LP108 o/s 19/21 Moorhills Road



We have spoken with UKPN and been advised that this is being arranged for week beginning 21st March 2022. They are being pressed to offer an earlier date.

4. WSL 19.4 LP085 Moorhills/Moorlands/ Moorlands Road junction.



We have spoken with UKPN and been advised that this is being arranged for week beginning 21st March 2022. They are being pressed to offer an earlier date.

5. WSL 21.1 LP153 o/s 44 Dormer Avenue.



- The Council now has an Asset Owners Agreement in place. The paperwork is now in hand to employ an alternative ICP for supply connections to the streetlights.

Faulty/ failed lights

1. SF21.3 LP090 o/s 57 Moorlands Road.




This was attended by a contractor and found to have a dead supply and damaged door. The door has been fixed back and cable tied but the dead supply needs to be attended by UKPN. This has been reported to UKPN. The need for a more permanent repair to the door is being investigated.

2. WSF 21.5 LP125 o/s 15 Wantage Crescent.



This is believed to possibly have been disconnected in error by Sparkx who were requested to carry out an emergency disconnection of the flashing lamp outside **16 Wantage Close**. Sparkx have been requested to confirm that they have reconnected the light they disconnected in error. It has not been reported as a fault for repair at this stage. An inspection is being carried out to establish whether this has been completed.

3. Small roundabout coming into Wing, junction of Stewkley.



Contractors have been working on these lights. It is understood that these have now been replaced and reconnected.

John Furniss

Deputy Clerk
Wing Parish Council

21st January 2022