

Street lighting update. 23/3/22

Replacement lights for reconnection.

A formal complaint has been submitted to UKPN.

1. WSL 19.3 LP061 o/s 13 Leighton Road



UKPN Faults have been asked for an update on this. Several requests have been made for advice on this. No further update available at this time.

2. WSL 20.1 LP 059 o/s 39 Leighton Road



We have received an updated quote from UKPN and are taking steps to arrange this reconnection.(see * under WSL 21.1 LP153 o/s 44 Dormer Avenue below)

3. WSL 19.2 LP108 o/s 19/21 Moorhills Road



We have spoken with UKPN and been advised that this was completed today, 23rd March 2022. CuPhosco have been advised and are due to attend to reconnect and commission the lantern tomorrow 24th March.

4. WSL 19.4 LP085 Moorhills/Moorlands/ Moorlands Road junction.



We have spoken with UKPN today, 23rd March 2022 and been advised that this requires a replacement part to be fitted to the column before there reconnection can be completed. CuPhosco have been advised and are due to attend tp fit the part tomorrow and hopefully complete the reinstatement tomorrow. We are monitoring the situation.

5. WSL 21.1 LP153 o/s 44 Dormer Avenue.



- The Council now has an Asset Owners Agreement in place. The paperwork is now in hand to employ an alternative ICP for supply connections to the streetlights. We are awaiting response from Sparkx Ltd to enable us to issue instructions to them to complete the works.

Faulty/ failed lights

1. SF21.3 LP090 o/s 57 Moorlands Road.



This was attended by a contractor and found to have a dead supply and damaged door. The door has been fixed back and cable tied but the dead supply needs to be attended by UKPN. This has been reported to UKPN. The need for a more permanent repair to the door is being investigated. No further information is available at this stage. An inspection is being carried out to establish whether this has been completed.

2. WSF 21.5 LP125 o/s 15 Wantage Crescent.



This is believed to possibly have been disconnected in error by Sparkx who were requested to carry out an emergency disconnection of the flashing lamp outside **16 Wantage Close**. Sparkx have been requested to confirm that they have reconnected the light they disconnected in error. It has not been reported as a fault for repair at this stage.

An inspection is being carried out to establish whether this has been completed.

No further information is available at this stage.

John Furniss

Deputy Clerk
Wing Parish Council

23 March 2022