

Street lighting update. 15/4/22

Replacement lights for reconnection.

A formal complaint has been submitted to UKPN.

UKPN have been advised that some items have been completed and requested to provide an update on other items.

1. WSL 19.3 LP061 o/s 13 Leighton Road



UKPN Faults have been in contact from site and have had to postpone the works due to the gas board working in the area. We will let the UKPN operatives know that the site is available to them again as soon as we are aware.

2. WSL 20.1 LP 059 o/s 39 Leighton Road



We have received confirmation from Sparkx Ltd that the arrangements with UKPN for Sparkx to complete these works as an ICP are now fully in place and the works are being booked in. We await notification of the date.

3. WSL 19.2 LP108 o/s 19/21 Moorhills Road



This streetlight was inspected and confirmed as operational again on 24th March.

4. WSL 19.4 LP085 Moorhills/Moorlands/ Moorlands Road junction.



This streetlight was inspected and confirmed as operational again on 26th March.

5. WSL 21.1 LP153 o/s 44 Dormer Avenue.



We have received confirmation from Sparkx Ltd that the arrangements with UKPN for Sparkx to complete these works as an ICP are now fully in place and the works are being booked in. We await notification of the date.

Faulty/ failed lights

1. SF21.3 LP090 o/s 57 Moorlands Road.



This was confirmed to be working when inspected.

2. WSF 21.5 LP125 o/s 15 Wantage Crescent.



This was confirmed to be working when inspected.

3. **LP111 Moorhills Road** (behind 1/3 William Bandy Close)



This has been reported as not working, again. It was last repaired in November 2021 and has been referred to the contractors.

John Furniss

Deputy Clerk
Wing Parish Council

15 April 2022