

Street lighting update. 28/6/22

Replacement lights for reconnection.

The formal complaint submitted to UKPN is ongoing.

1. WSL 19.3 LP061 o/s 13 Leighton Road



UKPN Faults have been contacted again about the delays in completing this work. It is linked to the ongoing complaint.

2. WSL 20.1 LP 059 o/s 39 Leighton Road



Reconnection complete. Light operational.


3. WSL 21.1 LP153 o/s 44 Dormer Avenue.



Reconnection complete. Light operational. Old column removed.

Faulty/ failed lights

1. LP111 Moorhills Road (behind 1/3 William Bandy Close)



This was confirmed to be working when inspected.

2. LP098 Opposite 3 Moorlands Road



We received a report that workman had been seen in the vicinity of this lamp since when it had not been lit. Sparkx Ltd were requested to attend and have reconnected the supply.

John Furniss

Deputy Clerk

Wing Parish Council

28 June 2022